Play Area / Equipment Operational Inspection

LLANHARRY COMMUNITY COUNCIL

Complete

Score	7 / 8 (87.5%)	Flagged items	0	Actions	0

Document No.	000078
Audit Title	LLANHARRY COMMUNITY COUNCIL
Client / Site	Llanharry Recreation Ground
Conducted on	26.06.2026 13:30 BST
Prepared by	Jerry Widdas
Location	Llanharry

Personnel

Jerry Widdas

Audit

7 / 8 (87.5%)

GENERAL SITE DESCRIPTION

1 / 1 (100%)

Detail:

Yes

The recreation ground consists of a play area fenced by steel bow top fencing with self closing gates
A MUGA kick about area and a youth shelter
Both areas are accessed by Tarmac pathways
Benches and picnic tables are located within the play area and also outside the play area boundary


Photo 1


Photo 2


Photo 3


Photo 4


Photo 5

ITEM

5 / 6 (83.33%)

Manufacturer identification and date of installation

Yes

MUGA area supplied by PPL date unknown
1 X 2 seat swing supplied and installed by Urban Recreation in 2016
1 X Traditional cradle seat swing Wicksteed Leisure
1 X Traditional Igloo climber Wicksteed Leisure
1 X Wheelchair roundabout supplied and installed Urban Recreation Dec 2018
1 X Multiplayer Unit Proludic installed Feb 2022
1 X Steel cable ride Record Play
1 X Freestanding slide Record Play
2 X Spring animals Fahr Industries installed Feb 2022
1 X Teen Shelter David Ogilvie Engineering
1 X Cantilever Swing supplied Urban Recreation 2016
9 X Fitness Items supplied Urban Recreation October 2017
1 X Spinning Cup supplied and installed Urban Recreation Dec 2018


Photo 6


Photo 7


Photo 8


Photo 9


Photo 10


Photo 11


Photo 12


Photo 13


Photo 14


Photo 15


Photo 16


Photo 17


Photo 18


Photo 19


Photo 20


Photo 21

Item Condition

Safe

At the time of inspection all the equipment was found to be in a safe and useable condition

Safety Surfacing

Safe

All items of play equipment are located on wet pour rubber safety surfacing.



Photo 22


Photo 23


Photo 24

Equipment Findings

At Risk

There is a muddy hole next to the cable ride ramp
There is underlying corrosion on one of the cradle seats, monitor


Photo 25


Photo 26

Safety Surfacing Findings

Safe

At the time of inspection all surfaces were found to be in a safe and useable condition
although there are some areas of joint separation which should be monitored

One corner of the roundabout surfacing has been subsiding over the years and continues to drop monitor


Photo 27


Photo 28


Photo 29


Photo 30


Photo 31

Recommendations

Yes

b

Other comments

1 / 1 (100%)

Yes

New cable guards, ramp treads and swing chains fitted
MUGA panel has been straightened and new bearings fitted to basket swing
Schedule inspection for 28th July


Photo 32


Photo 33


Photo 34

Inspector Sign Off



Jerry Widdas Routine And Operational Inspector (Cert OP9635)
17.07.2026 14:45 BST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34